


COFC



## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

**The application of:** Prindiville et al.**Date Mailed** January 12, 2006**Patent No.** 6,891,108**Issued:** May 10, 2005**Application No.** 09/971,985**Filed:** October 4, 2001**Confirmation No.** 4109**For:** SEMICONDUCTOR PACKAGES AND  
METHODS FOR MAKING THE SAME**Examiner:** Jeremy C. Norris**Art Unit:** 2841**Attorney Reference No.** 6047-61246-01**Certificate**

JAN 20 2006

**of Correction**

COMMISSIONER FOR PATENTS  
P.O. BOX 1450  
ALEXANDRIA, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION

The following errors were noted in the printed patent:

Cover Page:

Column 1, under "References Cited," add the following references (which were acknowledged by the Examiner on 10/17/03):

5,475,918	12/1995	Kubota et al
5,696,033	12/1997	Kinsman,
5,715,143	2/1998	McHugh et al
5,789,803	8/1988	Kinsman
5,952,611	9/1999	Eng et al.
5,953,216	9/1999	Farnsworth et al.
5,998,860	12/1999	Chan et al
6,013,535	1/2000	Moden et al.
6,017,776	1/2000	Jiang et al.
6,021,563	2/2000	Heo et al.
6,023,666	2/2000	Jiang et al.
6,048,755	4/2000	Jiang et al.
6,060,339	5/2000	Akram et al.
6,084,311	7/2000	Jiang et al.

100.00 US

01/17/2006 HUONG1 00000080 6891108

01 FC:1611

JAN 31 2006

6,091,136	7/2000	Jiang et al.
6,091,140	7/2000	Toh et al.
6,098,278	8/2000	Vindasius et al.
6,110,805	8/2000	Schrock et al.
6,111,324	8/2000	Sheppard et al.
6,201,299	3/2001	Tao et al.
6,218,731	4/2001	Huang et al.
6,265,766	7/2001	Moden
6,303,997	10/2001	Lee
6,326,700	12/2001	Bai et al.
6,331,451	12/2001	Fusaro et al.

In the Specification:

Column 4, line 67, "convention slot widths" should be --conventional slot widths-- (application, page 7, line 29).

Column 5, line 34, "opening (see" should be --opening) (see-- (application, page 8, line 24).

Column 5, line 51, "operational die" should be --operational dies-- (application, page 9, line 7).

Column 6, line 5, "die sites" should be --die sites)-- (application, page 9, line 25).

Column 6, line 27, "functional dies sites" should be --functional die sites-- (application, page 10, line 12).

A Certificate of Correction is enclosed to make formal notice of the errors in the referenced patent. Our check in the amount of \$100.00 is enclosed.


Please return the enclosed postcard to confirm that these documents have been received.

Respectfully submitted,

One World Trade Center, Suite 1600  
121 S.W. Salmon Street  
Portland, Oregon 97204  
Telephone: (503) 595-5300  
Facsimile: (503) 595-5301  
cc: Client  
Docketing

KLARQUIST SPARKMAN, LLP

By

  
Donald L. Stephens Jr.  
Registration No. 34,022

JAN 31 2006

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,891,108

DATED : May 10, 2005

INVENTOR(S) : Prindiville et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Cover Page, References Cited

5,475,918	12/1995	Kubota et al
5,696,033	12/1997	Kinsman,
5,715,143	2/1998	McHugh et al
5,789,803	8/1988	Kinsman
5,952,611	9/1999	Eng et al.
5,953,216	9/1999	Farnsworth et al.
5,998,860	12/1999	Chan et al
6,013,535	1/2000	Moden et al.
6,017,776	1/2000	Jiang et al.
6,021,563	2/2000	Heo et al.
6,023,666	2/2000	Jiang et al.
6,048,755	4/2000	Jiang et al.
6,060,339	5/2000	Akram et al.
6,084,311	7/2000	Jiang et al.
6,091,136	7/2000	Jiang et al.
6,091,140	7/2000	Toh et al.
6,098,278	8/2000	Vindasius et al.
6,110,805	8/2000	Schrock et al.
6,111,324	8/2000	Sheppard et al.
6,201,299	3/2001	Tao et al.
6,218,731	4/2001	Huang et al.
6,265,766	7/2001	Moden
6,303,997	10/2001	Lee
6,326,700	12/2001	Bai et al.
6,331,451	12/2001	Fusaro et al.

Column 4,

Line 67, "convention slot widths" should be --conventional slot widths--.

Column 5,

Line 34, "opening (see" should be --opening) (see--.

Line 51, "operational die" should be --operational dies--.

Column 6,

Line 5, "die sites" should be --die sites)--.

Line 27, "functional dies sites" should be --functional die sites--.

MAILING ADDRESS OF SENDER:

Klarquist Sparkman, LLP  
One World Trade Center, Suite 1600  
121 SW Salmon Street  
Portland, Oregon 97204

PATENT NO. 6,891,108

No. of add'l copies \_\_\_\_\_  
(@ .30 per page)

Page 1 of 1

JAN 31 2006